

Oil Field Environmental Incident Summary

Incident: 20160308115505

Date/Time of Notice: 03/08/2016 11:55

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: CHAMELEON STATE 21-16-1H

Field Name: BANKS

Well File #: 31795

Date Incident: 3/8/2016

Time Incident: 04:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 97

Sec: 16

Qtr: NW NW

Location Description:

Submitted By: Sarah Paycer

Received By:

Contact Person: Sarah Paycer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Gallons	1	Gallons	1	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/11/2016

Clean Up Concluded: 3/8/2016

Risk Evaluation:

None noted.

Areal Extent:

15'x25' area on the South side of the pad.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The fire was immediately extinguished. No fluids remained after the fire was put out. Vegetation is expected to recover without any further remediation.

Wastes Disposal Location: Approved Disposal Facility

Agencies Involved: NDIC
State Trust Lands Department

Updates

Date: 3/8/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release impacted an area off the well pad. Incident report forwarded to field inspector for additional follow-up.

Date: 3/9/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site, 12:00 p.m. Wind 10-15 mph, 45 degrees F. Fire occurred off location and burned an approximate 10- x 50-foot area. Release was due to excess pressure released to the flare during maintenance. Fire burned up all remaining product, and I did not see any other visual contamination present. Follow-up required to check on vegetative growth

Date: 6/2/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 8:05 a.m. Wind 0-5 mph, 60 degrees.

Fire impact area just off of location has significant vegetative growth. Location is to the NW of two horizontal treaters with fire tubes. Vegetative growth is sparse throughout affected area. Follow-up is necessary to check on future vegetative growth. Check next spring.